

---

# Standard Minimum PPE Requirements

For a TOUR or SITE WALK on the perimeter of  
the plant, please wear:

Safety Glasses

Hard Hat

Sturdy Shoes

For a more detailed TOUR or INSPECTION that  
requires going onto the structure, please  
include:

Safety Toed Shoes

Leather Gloves on person

Hearing protection as necessary

When PERFORMING an INTERNAL INSPECTION or ANY OTHER WORK in the plant  
as part of the demolition, wear all appropriate PPE according to the job at hand  
and your experience and training dictates

this is not limited to:

All the PPE listed above

Long Sleeve Shirt / Jacket

Goggles / Face Shield

Respiratory Protection

Welding / Cutting Leathers or other PPE

Disposable Coveralls

Chemical Resistant Gear